


# Higgins Lake Dam Data

for September 2010



Day	Gate 1	Gate 2	Gate 3	Gate 4	Gate 5	Gate 6	Rain	Temp	Staff gage
W 1	C	C	C	C	C	C		74°	5.24
Th 2	C	C	C	C	C	C	.04	73°	5.23
F 3	C	C	C	C	C	C	1.50	61°	5.34
S 4	C	C	C	C	C	C	.12		5.32
S 5	C	C	C	C	C	C	.24		5.32
M 6	C	C	C	C	C	C	.06		5.31
T 7	C	C	C	C	C	C	.23	72°	5.29
W 8	C	C	C	C	C	C	.02	59°	5.28
Th 9	C	C	C	C	C	C	.03	62°	5.27
F 10	C	C	C	C	C	C			5.24
S 11	C	C	C	C	C	C			5.24
S 12	C	C	C	C	C	C			5.25
M 13	C	C	C	C	C	C			5.23
T 14	C	C	C	C	C	C		65°	5.24
W 15	C	C	C	C	C	C		63°	5.22
Th 16	C	C	C	C	C	O	.58	55°	5.20
F 17	C	C	C	C	C	O	.04	63°	5.21
S 18	C	C	C	C	C	O			5.21
S 19	C	C	C	C	C	O	.38		5.22
M 20	C	C	C	C	C	O		63°	5.20
T 21	C	C	C	C	C	O		79°	5.17
W 22	C	C	C	C	C	O	.06	73°	5.18
Th 23	C	O	O	O	O	O	.03	72°	5.17
F 24	C	O	O	O	O	O	.72	61°	5.22
S 25	C	O	O	O	O	O	.02		5.21
S 26	C	O	O	O	O	O	.01		5.19
M 27	C	O	O	O	O	O		57°	5.16
T 28	C	O	O	O	O	O		62°	5.14
W 29	C	O	O	O	O	O		62°	5.12
Th 30	C	O	O	O	O	O	.03	65°	5.07
31									

\* Beginning of gage malfunction thru Oct. 4